



# ENAPART



93 S Railroad Avenue Unit C  
Bergenfield NJ 07621 USA  
[www.enapart.com](http://www.enapart.com)  
[sales@enapart.com](mailto:sales@enapart.com)



Via del Canneto 35,  
Borgosatollo, Brescia - Italia  
[www.enapart.it](http://www.enapart.it)  
[vendite@enapart.it](mailto:vendite@enapart.it)



Barbaros Mah. Ihlamur Bul. Aĝaoĝlu  
My Newwork No:3/15 Ataşehir / İstanbul  
[www.enapart.net](http://www.enapart.net)  
[satis@enapart.net](mailto:satis@enapart.net)



PRIVADA 10 B SUR #3908 COL.  
ANZUREZ, C.P. 72530, PUEBLA, PUE  
[www.enapart.com.mx](http://www.enapart.com.mx)  
[sales@enapart.com.mx](mailto:sales@enapart.com.mx)



Friedrich-Ebert-Anlage 36, 60325  
Frankfurt am Main, Germany  
[www.enapart.de](http://www.enapart.de)  
[anfrage@enapart.de](mailto:anfrage@enapart.de)



4 boulevard Carnot, 95400  
villiers-le-bel, Paris, France  
[www.enapart.fr](http://www.enapart.fr)  
[sales@enapart.fr](mailto:sales@enapart.fr)



65049, ОДЕСА, ВУЛИЦЯ ІВАНА  
ФРАНКА, БУДИНОК 55, ПОВЕРХ 3  
[www.enapart.com.ua](http://www.enapart.com.ua)  
[sales@enapart.com.ua](mailto:sales@enapart.com.ua)



MUNICIPIUL BUCUREȘTI, SECTOR 3,  
B-DUL BASARABIA, NR.250, CORP P+5  
[www.enapart.ro](http://www.enapart.ro)  
[sales@enapart.ro](mailto:sales@enapart.ro)



〒584-0023 大阪府富田林市若松町  
東2丁目2番16号  
[www.enapart.co.jp](http://www.enapart.co.jp)  
[sales@enapart.co.jp](mailto:sales@enapart.co.jp)



PLAZA NUESTRA SEÑORA DE LAS  
NIEVES 12 ,LOCAL ,50012,ZARAGOZA  
[www.enapart.es](http://www.enapart.es)  
[ventas@enapart.es](mailto:ventas@enapart.es)



Складова база „Онгъл“, Склад А2, п.к.  
4006, гр. Пловдив, България  
[www.enapart.bg](http://www.enapart.bg)  
[sales@enapart.bg](mailto:sales@enapart.bg)



3 Austin Mews, High Street, Hemel  
Hempstead, HP1 3AF , United Kingdom  
[www.enapart.co.uk](http://www.enapart.co.uk)  
[sales@enapart.co.uk](mailto:sales@enapart.co.uk)

## STANDARD FANS

|              |          |          |
|--------------|----------|----------|
| D20E01LWBA00 | 20x20x10 | 5 Vd.c.  |
| D20E01MWBA00 | 20x20x10 | 5 Vd.c.  |
| D20E04LWBA00 | 20x20x10 | 12 Vd.c. |
| D20E04MWBA00 | 20x20x10 | 12 Vd.c. |
| D02E01HWBZ00 | 25x25x10 | 5 Vd.c.  |
| D02E01MWBZ00 | 25x25x10 | 5 Vd.c.  |
| D02E04HWBZ00 | 25x25x10 | 12 Vd.c. |
| D02E04MWBZ00 | 25x25x10 | 12 Vd.c. |
| D03E01LWBA00 | 30x30x10 | 5 Vd.c.  |
| D03E01MWBA00 | 30x30x10 | 5 Vd.c.  |
| D03E04LWBA00 | 30x30x10 | 12 Vd.c. |
| D03E04MWBA00 | 30x30x10 | 12 Vd.c. |
| D04E01HWBT00 | 40x40x10 | 5 Vd.c.  |
| D04E01HWST00 | 40x40x10 | 5 Vd.c.  |
| D04E04MWBT00 | 40x40x10 | 12 Vd.c. |
| D04E04MWST00 | 40x40x10 | 12 Vd.c. |
| D04E05HWBT00 | 40x40x10 | 24 Vd.c. |
| D04E05HWST00 | 40x40x10 | 24 Vd.c. |
| D04E05MWBT00 | 40x40x10 | 24 Vd.c. |
| D04E05MWST00 | 40x40x10 | 24 Vd.c. |
| D04E04HWST00 | 40x40x10 | 12 Vd.c. |
| D04E01MWST00 | 40x40x10 | 5 Vd.c.  |
| D04F04HWBA00 | 40x40x15 | 12 Vd.c. |
| D04F04HWSA00 | 40x40x15 | 12 Vd.c. |
| D04F04LWBA00 | 40x40x15 | 12 Vd.c. |
| D04F04LWSA00 | 40x40x15 | 12 Vd.c. |
| D04F04MWBA00 | 40x40x15 | 12 Vd.c. |
| D04F04MWSA00 | 40x40x15 | 12 Vd.c. |
| D04D04HWBZ00 | 40x40x20 | 12 Vd.c. |
| D04D04MWBZ00 | 40x40x20 | 12 Vd.c. |
| D04D04MWSZ00 | 40x40x20 | 12 Vd.c. |
| D04D05HWBZ00 | 40x40x20 | 24 Vd.c. |
| D04D05MWBZ00 | 40x40x20 | 24 Vd.c. |
| D04D04HWSZ00 | 40x40x20 | 12 Vd.c. |
| D04D05MWSZ00 | 40x40x20 | 24 Vd.c. |
| D04D05HWSZ00 | 40x40x20 | 24 Vd.c. |
| D45E01HWBA00 | 45x45x10 | 5 Vd.c.  |
| D45E01MWBA00 | 45x45x10 | 5 Vd.c.  |
| D45E04HWBA00 | 45x45x10 | 12 Vd.c. |
| D45E04HWSA00 | 45x45x10 | 12 Vd.c. |
| D45E04MWBA00 | 45x45x10 | 12 Vd.c. |
| D45E04MWSA00 | 45x45x10 | 12 Vd.c. |
| D45E01MWSA00 | 45x45x10 | 5 Vd.c.  |
| D45E01HWSA00 | 45x45x10 | 5 Vd.c.  |
| D50E04LWBA00 | 50x50x10 | 12 Vd.c. |
| D50E04LWSA00 | 50x50x10 | 12 Vd.c. |
| D50E04MWBA00 | 50x50x10 | 12 Vd.c. |
| D50E04MWSA00 | 50x50x10 | 12 Vd.c. |
| D50F04HWBA00 | 50x50x15 | 12 Vd.c. |
| D50F04SWBA00 | 50x50x15 | 12 Vd.c. |

|              |          |          |
|--------------|----------|----------|
| D50F04SWSA00 | 50x50x15 | 12 Vd.c. |
| D50F04LWSA00 | 50x50x15 | 12 Vd.c. |
| D50F04MWSA00 | 50x50x15 | 12 Vd.c. |
| D50F04HWSA00 | 50x50x15 | 12 Vd.c. |
| D06E01MWBT00 | 60x60x10 | 5 Vd.c.  |
| D06E01MWST00 | 60x60x10 | 5 Vd.c.  |
| D06E04MWST00 | 60x60x10 | 12 Vd.c. |
| D06E04HWST00 | 60x60x10 | 12 Vd.c. |
| D06E01HWST00 | 60x60x10 | 5 Vd.c.  |
| D06F01MWBA00 | 60x60x15 | 5 Vd.c.  |
| D06F01MWSA00 | 60x60x15 | 5 Vd.c.  |
| D06F04MWBA00 | 60x60x15 | 12 Vd.c. |
| D06F04MWSA00 | 60x60x15 | 12 Vd.c. |
| D06F05HWBA00 | 60x60x15 | 24 Vd.c. |
| D06F05MWBA00 | 60x60x15 | 24 Vd.c. |
| D06F05MWSA00 | 60x60x15 | 24 Vd.c. |
| D06F04HWSA00 | 60x60x15 | 12 Vd.c. |
| D06F05HWSA00 | 60x60x15 | 24 Vd.c. |
| D06F01HWSA00 | 60x60x15 | 5 Vd.c.  |
| D06D04HWBA00 | 60x60x20 | 12 Vd.c. |
| D06D04HWSA00 | 60x60x20 | 12 Vd.c. |
| D06D04LWBA00 | 60x60x20 | 12 Vd.c. |
| D06D04LWSA00 | 60x60x20 | 12 Vd.c. |
| D06D04MWBA00 | 60x60x20 | 12 Vd.c. |
| D06D04MWSA00 | 60x60x20 | 12 Vd.c. |
| D06D05LWBA00 | 60x60x20 | 24 Vd.c. |
| D06D05LWSA00 | 60x60x20 | 24 Vd.c. |
| D06D05MWBA00 | 60x60x20 | 24 Vd.c. |
| D06D05MWSA00 | 60x60x20 | 24 Vd.c. |
| D06A04LWBA00 | 60x60x25 | 12 Vd.c. |
| D06A04MWBA00 | 60x60x25 | 12 Vd.c. |
| D06A04SWBA00 | 60x60x25 | 12 Vd.c. |
| D06A05HWBA00 | 60x60x25 | 24 Vd.c. |
| D06A05HWSA00 | 60x60x25 | 24 Vd.c. |
| D06A05SWBA00 | 60x60x25 | 24 Vd.c. |
| D06A04HWSA00 | 60x60x25 | 12 Vd.c. |
| D06A04SWSA00 | 60x60x25 | 12 Vd.c. |
| D06A04LWSA00 | 60x60x25 | 12 Vd.c. |
| D06A04MWSA00 | 60x60x25 | 12 Vd.c. |
| D06A05SWSA00 | 60x60x25 | 24 Vd.c. |
| D06A05LWSA00 | 60x60x25 | 24 Vd.c. |
| D06A05MWSA00 | 60x60x25 | 24 Vd.c. |
| D07A04MWBA00 | 70x70x25 | 12 Vd.c. |
| D07A04MWSA00 | 70x70x25 | 12 Vd.c. |
| D07A05HWBA00 | 70x70x25 | 24 Vd.c. |
| D07A05HWSA00 | 70x70x25 | 24 Vd.c. |
| D07A05MWBA00 | 70x70x25 | 24 Vd.c. |
| D07A05MWSA00 | 70x70x25 | 24 Vd.c. |
| D07A04HWSA00 | 70x70x25 | 12 Vd.c. |
| D08F01MWBA00 | 80x80x15 | 5 Vd.c.  |
| D08F01MWSA00 | 80x80x15 | 5 Vd.c.  |
| D08F04HWBA00 | 80x80x15 | 12 Vd.c. |

|              |          |          |
|--------------|----------|----------|
| D08F04HWSA00 | 80x80x15 | 12 Vd.c. |
| D08F04MWBA00 | 80x80x15 | 12 Vd.c. |
| D08F05MWBA00 | 80x80x15 | 24 Vd.c. |
| D08F05MWSA00 | 80x80x15 | 24 Vd.c. |
| D08F04MWSA00 | 80x80x15 | 12 Vd.c. |
| D08F05HWSA00 | 80x80x15 | 24 Vd.c. |
| D08F01HWSA00 | 80x80x15 | 5 Vd.c.  |
| D08D04HWBA00 | 80x80x20 | 12 Vd.c. |
| D08D04MWBA00 | 80x80x20 | 12 Vd.c. |
| D08D04MWSA00 | 80x80x20 | 12 Vd.c. |
| D08D05HWBA00 | 80x80x20 | 24 Vd.c. |
| D08D05MWBA00 | 80x80x20 | 24 Vd.c. |
| D08D05MWSA00 | 80x80x20 | 24 Vd.c. |
| D08D04HWSA00 | 80x80x20 | 12 Vd.c. |
| D08D05HWSA00 | 80x80x20 | 24 Vd.c. |
| D08A04HWBAF0 | 80x80x25 | 12 Vd.c. |
| D08A04LWBA00 | 80x80x25 | 12 Vd.c. |
| D08A04LWSA00 | 80x80x25 | 12 Vd.c. |
| D08A04MWBA00 | 80x80x25 | 12 Vd.c. |
| D08A04SWBA00 | 80x80x25 | 12 Vd.c. |
| D08A04SWSA00 | 80x80x25 | 12 Vd.c. |
| D08A05HWBA00 | 80x80x25 | 24 Vd.c. |
| D08A05HWSA00 | 80x80x25 | 24 Vd.c. |
| D08A05MWBA00 | 80x80x25 | 24 Vd.c. |
| D08A05SWBA00 | 80x80x25 | 24 Vd.c. |
| D08A05SWSA00 | 80x80x25 | 24 Vd.c. |
| D08A04MWBA00 | 80x80x25 | 12 Vd.c. |
| D08A04MWSA00 | 80x80x25 | 12 Vd.c. |
| D08A04HWBAF0 | 80x80x25 | 12 Vd.c. |
| D08A04HWSA00 | 80x80x25 | 12 Vd.c. |
| D08A05MWSA00 | 80x80x25 | 24 Vd.c. |
| D08A05LWSA00 | 80x80x25 | 24 Vd.c. |
| D08A05HWSA00 | 80x80x25 | 24 Vd.c. |
| D09D04MWBA00 | 92x92x20 | 12 Vd.c. |
| D09D04MWSA00 | 92x92x20 | 12 Vd.c. |
| D09D05MWBA00 | 92x92x20 | 24 Vd.c. |
| D09D05MWSA00 | 92x92x20 | 24 Vd.c. |
| D09D04HWSA00 | 92x92x20 | 12 Vd.c. |
| D09D05HWSA00 | 92x92x20 | 24 Vd.c. |
| D09A04EWBZ00 | 92x92x25 | 12 Vd.c. |
| D09A04HWBZ00 | 92x92x25 | 12 Vd.c. |
| D09A04HWSZ00 | 92x92x25 | 12 Vd.c. |
| D09A04LWBZ00 | 92x92x25 | 12 Vd.c. |
| D09A04LWSZ00 | 92x92x25 | 12 Vd.c. |
| D09A04MWBZ00 | 92x92x25 | 12 Vd.c. |
| D09A04MWSZ00 | 92x92x25 | 12 Vd.c. |
| D09A04SWBZ00 | 92x92x25 | 12 Vd.c. |
| D09A05HWBZ00 | 92x92x25 | 24 Vd.c. |
| D09A05LWBZ00 | 92x92x25 | 24 Vd.c. |
| D09A05LWSZ00 | 92x92x25 | 24 Vd.c. |
| D09A05MWBZ00 | 92x92x25 | 24 Vd.c. |
| D09A05MWSZ00 | 92x92x25 | 24 Vd.c. |

|              |            |          |
|--------------|------------|----------|
| D09A05SWBZ00 | 92x92x25   | 24 Vd.c. |
| D09A04SWSZ00 | 92x92x25   | 12 Vd.c. |
| D09A05SWSZ00 | 92x92x25   | 24 Vd.c. |
| D09A05HWSZ00 | 92x92x25   | 24 Vd.c. |
| D12A04LWBZ00 | 120x120x25 | 12 Vd.c. |
| D12A04MWBZ00 | 120x120x25 | 12 Vd.c. |
| D12A04SWBZ00 | 120x120x25 | 12 Vd.c. |
| D12A04SWSZ00 | 120x120x25 | 12 Vd.c. |
| D12A05HWBZ00 | 120x120x25 | 24 Vd.c. |
| D12A05LWBZ00 | 120x120x25 | 24 Vd.c. |
| D12A05LWSZ00 | 120x120x25 | 24 Vd.c. |
| D12A05MWBZ00 | 120x120x25 | 24 Vd.c. |
| D12A05MWSZ00 | 120x120x25 | 24 Vd.c. |
| D12A05SWBZ00 | 120x120x25 | 24 Vd.c. |
| D12A04MWSZ00 | 120x120x25 | 12 Vd.c. |
| D12A04HWSZ00 | 120x120x25 | 12 Vd.c. |
| D12A04LWSZ00 | 120x120x25 | 12 Vd.c. |
| D12A05HWSZ00 | 120x120x25 | 24 Vd.c. |
| D12A05SWSZ00 | 120x120x25 | 24 Vd.c. |
| D12G05HWBA00 | 120x120x32 | 24 Vd.c. |
| D12B04HWBZ00 | 120x120x38 | 12 Vd.c. |
| D12B04LWBZ00 | 120x120x38 | 12 Vd.c. |
| D12B04SWBZ00 | 120x120x38 | 12 Vd.c. |
| D12B04SWSZ00 | 120x120x38 | 12 Vd.c. |
| D12B05HWBZ00 | 120x120x38 | 24 Vd.c. |
| D12B05HWSZ00 | 120x120x38 | 24 Vd.c. |
| D12B05LWBZ00 | 120x120x38 | 24 Vd.c. |
| D12B05LWSZ00 | 120x120x38 | 24 Vd.c. |
| D12B05MWBZ00 | 120x120x38 | 24 Vd.c. |
| D12B05MWSZ00 | 120x120x38 | 24 Vd.c. |
| D12B05SWBZ00 | 120x120x38 | 24 Vd.c. |
| D12B07HWBZ00 | 120x120x38 | 48 Vd.c. |
| D12B07LWBZ00 | 120x120x38 | 48 Vd.c. |
| D12B07LWSZ00 | 120x120x38 | 48 Vd.c. |
| D12B07MWBZ00 | 120x120x38 | 48 Vd.c. |
| D12B04LWSZ00 | 120x120x38 | 12 Vd.c. |
| D12B04MWSZ00 | 120x120x38 | 12 Vd.c. |
| D12B04HWSZ00 | 120x120x38 | 12 Vd.c. |
| D12B05HWSZ00 | 120x120x38 | 24 Vd.c. |
| D12B05SWSZ00 | 120x120x38 | 24 Vd.c. |
| D12B07MWSZ00 | 120x120x38 | 48 Vd.c. |
| D12B07HWSZ00 | 120x120x38 | 48 Vd.c. |
| D22S07HKBD00 | 218x218x83 | 48 Vd.c. |